



Main

Accessory / separate part destination	Ultrasonic sensor
Product compatibility	XXS ultrasonic sensors XXA ultrasonic sensors
Accessory / separate part category	Configuration accessories
Accessory / separate part type	Configuration software

Complementary

Material	Plastic and metal
----------	-------------------

Environment

Ambient air temperature for storage	-20...45 °C
Ambient air temperature for operation	0...45 °C
Relative humidity	95 % without condensation

Disclaimer: This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications