



11-Apr-2019

PCN #:P-19-017201

Subject:AMP-LATCH series Connectors

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from <EBK Krüger GmbH & Co. KG Warthestraße 6 14513 Teltow Germany> to <EBK Krüger GmbH & Co. KG Großer Berliner Damm 99 12487 Berlin Germany>

Reason: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Key Dates:

Contact By Date:15-Jun-2019

Implementation Date:15-Jun-2019

Product Affected

3-1393531-3

(Alias Part Numbers:

"V23535A3280C261")

2-1393586-5

(Alias Part Numbers:

"V23535A2210A 61")

1393532-3

(Alias Part Numbers:

"C42334A 368A 16"

"C42334A368A16")

1-1393536-6

(Alias Part Numbers:

"V23535B1780C200")

2-1393536-1

(Alias Part Numbers:
"V23535B1780C500")
1393586-9
(Alias Part Numbers:
"V23535A2200A140")
3-1393586-9
(Alias Part Numbers:
"V23535A2210A260")
3-1393586-4
(Alias Part Numbers:
"V23535A2210A161")
2-1393531-5
(Alias Part Numbers:
"V23535A3280C 61"
"V23535A3280C61")
1393532-7
(Alias Part Numbers:
"C42334A 368A 24"
"C42334A368A24")
2-1393586-3
(Alias Part Numbers:
"V23535A2200A342")
3-1393586-6
(Alias Part Numbers:
"V23535A2210A200")
1393558-3
(Alias Part Numbers:
"C42334A 421C 41"
"C42334A421C41")
3-1393586-3
(Alias Part Numbers:
"V23535A2210A160")
1-1393586-2
(Alias Part Numbers:
"V23535A2200A160")
1-1393586-0
(Alias Part Numbers:

Product Affected

"V23535A2200A141")

1393536-5

(Alias Part Numbers:

"V23535B1780B260")

2-1393586-1

(Alias Part Numbers:

"V23535A2200A340")

4-1393586-1

(Alias Part Numbers:

"V23535A2210A262")

2-1393536-0

(Alias Part Numbers:

"V23535B1780C400")

1393532-5

(Alias Part Numbers:

"C42334A 368A 18"

"C42334A368A18")

4-1393586-4

(Alias Part Numbers:

"V23535A2210A342")

1393532-4

(Alias Part Numbers:

"C42334A 368A 17"

"C42334A368A17")

3-1393586-7

(Alias Part Numbers:

"V23535A2210A201")

1393558-5

(Alias Part Numbers:

"C42334A 421C 51"

"C42334A421C51")

1-1393586-6

(Alias Part Numbers:

"V23535A2200A201")

1393586-8

(Alias Part Numbers:

"V23535A2200A102")

1393586-4

(Alias Part Numbers:

"V23535A2200A 61")

Product Affected

4-1393586-0

(Alias Part Numbers:

"V23535A2210A261")

1-1393586-9

(Alias Part Numbers:

"V23535A2200A261")

3-1393586-0

(Alias Part Numbers:

"V23535A2210A140")

3-1393586-8

(Alias Part Numbers:

"V23535A2210A202")

1-1393536-4

(Alias Part Numbers:

"V23535B1780C140")

1-1393536-5

(Alias Part Numbers:

"V23535B1780C160")

2-1393536-2

(Alias Part Numbers:

"V23535B1780C600")

4-1393586-3

(Alias Part Numbers:

"V23535A2210A341")

1-1393586-8

(Alias Part Numbers:

"V23535A2200A260")

2-1393531-9

(Alias Part Numbers:

"V23535A3280C161")

2-1393531-6

(Alias Part Numbers:

"V23535A3280C101")

1-1393536-9

(Alias Part Numbers:

"V23535B1780C340")

3-1393586-2

(Alias Part Numbers:

"V23535A2210A142")

2-1393586-8

Product Affected

(Alias Part Numbers:
"V23535A2210A101")
1-1393536-2

(Alias Part Numbers:
"V23535B1780C 60"
"V23535B1780C60")
2-1393586-0

(Alias Part Numbers:
"V23535A2200A262")
1-1393586-5

(Alias Part Numbers:
"V23535A2200A200")
1393536-8

(Alias Part Numbers:
"V23535B1780B400")
2-1393586-2

(Alias Part Numbers:
"V23535A2200A341")
4-1393586-2

(Alias Part Numbers:
"V23535A2210A340")
1393558-4

(Alias Part Numbers:
"C42334A 421C 42"
"C42334A421C42")
2-1393586-4

(Alias Part Numbers:
"V23535A2210A 60"
"V23535A2210A60")
1393586-3

(Alias Part Numbers:
"V23535A2200A 60"
"V23535A2200A60")
3-1393531-5

(Alias Part Numbers:
"V23535A3280C401")
1-1393586-7

(Alias Part Numbers:
"V23535A2200A202")
1-1393536-3

Product Affected

(Alias Part Numbers:
"V23535B1780C100")
2-1393586-7

(Alias Part Numbers:
"V23535A2210A100")
1393532-2

(Alias Part Numbers:
"C42334A 368A 15"
"C42334A368A15")
1-1393586-3

(Alias Part Numbers:
"V23535A2200A161")
1-1393586-1

(Alias Part Numbers:
"V23535A2200A142")
3-1393531-9

(Alias Part Numbers:
"V23535A3280C601")
3-1393586-1

(Alias Part Numbers:
"V23535A2210A141")
1-1393536-8

(Alias Part Numbers:
"V23535B1780C320")
1393558-6

(Alias Part Numbers:
"C42334A 421C 52"
"C42334A421C52")
1393532-1

(Alias Part Numbers:
"C42334A 368A 14"
"C42334A368A14")
1-1393536-7

(Alias Part Numbers:
"V23535B1780C260")
1393586-6

(Alias Part Numbers:
"V23535A2200A100")
2-1393531-8

(Alias Part Numbers:

Product Affected

"V23535A3280C141")

4-1393531-0

(Alias Part Numbers:

"V23535A3280C641")

3-1393586-5

(Alias Part Numbers:

"V23535A2210A162")

1393586-7

(Alias Part Numbers:

"V23535A2200A101")

2-1393536-3

(Alias Part Numbers:

"V23535B1780C640")

3-1393531-1

(Alias Part Numbers:

"V23535A3280C201")

2-1393586-9

(Alias Part Numbers:

"V23535A2210A102")

3-1393531-7

(Alias Part Numbers:

"V23535A3280C501")

1-1393586-4

(Alias Part Numbers:

"V23535A2200A162")

3-1393531-4

(Alias Part Numbers:

"V23535A3280C341")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.