



Product Change Notification

Current Date: 08-Jun-2022

TE Connectivity

Product Change Notification: PCN-22-139601

PCN Date: 18-MAY-22

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: (Text limited to 120 characters)

Alternative material Vectra E130i is Laperos E130i.

Description of Changes

No changes of drawing, specification, function. P2 relays use Laperos E130i and Vectra E130i with have same properties.

Reason for Changes:

P2 relay use Vectra E130i and Laperos E130i. Both materials have the same characteristics, passed the same tests and are both UL certified. The relay form (dimensions), features and ratings keep unchanged.

PCN Attributes:

Product Category:

Relays, Contactors & Switches

Kind of Change:

Drawing

Change Feature:

Revision Adjustment

Potential Customer Impact:

No Customer Impact

Remarks:

P2 relay Vectra E130i to be changed to alternative material Laperos E130i .

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Ship Date of Changed Items (Changed Parts Only):

23-MAY-2022

Last Ship Date of Changed Items (Obsolete Parts Only):

31-DEC-2022

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Effectivity Date:

Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO			V23079A1003B301			
1-1393788-6	NO			V23079A1005B301			
1393788-3	NO			V23079A1001B301			
3-1393788-7	NO			V23079B1205B301			
3-1393789-5	NO			V23079A2001B301			
4-1393789-3	NO			V23079D2001B301			
4-1393789-5	NO			V23079D2003B301			
5-1393788-5	NO			V23079D1001B301			
5-1393788-8	NO			V23079D1005B301			
5-1393789-1	NO			V23079G2003B301			
5-1393789-4	NO			V23079G2008B301			
6-1393788-8	NO			V23079E1201B301			
6-1393788-9	NO			V23079E1203B301			