



12-Feb-2020

PCN #:E-20-001932

Subject:RYII relay series

Description of Change: Dear Customer, we would like to inform about the extension and modification of the certification VDE. The relay RY reflow version with welded contacts is completely covered by VDE approval. The certification HazLoc for the standard and reflow version of the relay RY (version RT II) was also added to VDE file.

Reason: Product Improvement.

Key Dates:

Contact By Date:17-May-2020

Implementation Date:17-May-2020

Product Affected

2-1393225-9

(Alias Part Numbers:

"RY612024")

6-1393224-0

(Alias Part Numbers:

"RY213005")

1415033-1

(Alias Part Numbers:

"RY6120124")

9-1415046-1

(Alias Part Numbers:

"RY900094")

1-1393225-4

(Alias Part Numbers:

"RY610024")

Product Affected

1-1393224-8

(Alias Part Numbers:

"RYA32024")

7-1393224-6

(Alias Part Numbers:

"RY531005")

1956164-2

(Alias Part Numbers:

"RY900122R(RY211006R)")

9-1393224-9

(Alias Part Numbers:

"RY551012")

1-1393224-3

(Alias Part Numbers:

"RYA31048")

4-1393224-6

(Alias Part Numbers:

"RY211012")

1-1393224-6

(Alias Part Numbers:

"RYA32012")

2-1393225-6

(Alias Part Numbers:

"RY612012"

"1SNE008000T1400")

4-1393225-9

(Alias Part Numbers:

"RY900045")

1-1956170-2

4-1393224-3

(Alias Part Numbers:

"RY211006")

2-1393224-6

(Alias Part Numbers:

"RYA51005")

3-1956170-2

5-1393224-1

(Alias Part Numbers:

"RY211048")

8-1393224-9

Product Affected

(Alias Part Numbers:

"RY533024")

6-1393224-2

(Alias Part Numbers:

"RY213024")

5-1393224-8

(Alias Part Numbers:

"RY212024")

2-1416010-9

(Alias Part Numbers:

"RY212060")

8-1393224-5

(Alias Part Numbers:

"RY532024")

4-1393224-9

(Alias Part Numbers:

"RY211024"

"E75193-000"

"AMPS-4-1393224-9")

2-1393225-1

(Alias Part Numbers:

"RY611024")

5-1419136-2

(Alias Part Numbers:

"RY613005")

1-1393224-4

(Alias Part Numbers:

"RYA32005")

6-1393225-3

(Alias Part Numbers:

"RY900065")

2-1393225-4

(Alias Part Numbers:

"RY612006")

4-1393225-5

(Alias Part Numbers:

"RY900021")

5-1393224-5

(Alias Part Numbers:

"RY212012")

Product Affected

1-1415033-1

(Alias Part Numbers:
"RY6120244")

1-1393225-7

(Alias Part Numbers:
"RY611005")

2-1415033-1

(Alias Part Numbers:
"RY6120484")

8-1393224-2

(Alias Part Numbers:
"RY531024")

3-1393225-3

(Alias Part Numbers:
"RY613024")

5-1393225-1

(Alias Part Numbers:
"RY900048")

1-1393224-2

(Alias Part Numbers:
"RYA31024")

4-1393224-7

(Alias Part Numbers:
"RY211018")

5-1393225-2

(Alias Part Numbers:
"RY900049")

1956164-1

2-1393224-1

(Alias Part Numbers:
"RYA33024")

8-1393224-3

(Alias Part Numbers:
"RY531048")

2-1393225-2

(Alias Part Numbers:
"RY611048")

3-1393225-1

(Alias Part Numbers:
"RY613012")

Product Affected

1-1956170-6

4-1393225-7

(Alias Part Numbers:

"RY900043")

7-1956150-2

9-1393224-0

(Alias Part Numbers:

"RY533048")

6-1393224-1

(Alias Part Numbers:

"RY213012")

2-1393225-3

(Alias Part Numbers:

"RY612005")

3-1956170-0

7-1393224-8

(Alias Part Numbers:

"RY531009")

1-1393225-9

(Alias Part Numbers:

"RY611012")

4-1393224-5

(Alias Part Numbers:

"RY211009")

4-1393224-2

(Alias Part Numbers:

"RY211005")

5-1393225-0

(Alias Part Numbers:

"RY900046")

5-1393224-2

(Alias Part Numbers:

"RY212005")

1393224-9

(Alias Part Numbers:

"RYA31012")

7-1393224-9

(Alias Part Numbers:

"RY531012")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.