



05-May-2020

PCN #:P-20-019022

Subject:TE Corcom P-Series Power Entry Modules

Description of Change: Product improvement to replace white ink stamped markings with laser markings on the fuseholder.

Reason: Product improvement.

Key Dates:

Contact By Date:08-May-2020

Implementation Date:08-May-2020

Product Affected

5-6609947-8

(Alias Part Numbers:
"PSJ0XSH3A")

6-6609107-6

(Alias Part Numbers:
"PS0SXDS3B")

4-6609106-6

(Alias Part Numbers:
"PS0SXDHX0")

6609100-2

(Alias Part Numbers:
"PE00XS000")

5-6609930-9

(Alias Part Numbers:
"PE00XSSX0")

6609106-8

(Alias Part Numbers:
"PS0SXSH60")

Product Affected

4-6609106-3

(Alias Part Numbers:
"PS00XDH30")

3-6609951-8

5-6609930-7

(Alias Part Numbers:
"PE00XSSXB")

5-6609930-3

(Alias Part Numbers:
"PE00XSH6B")

4-6609107-5

(Alias Part Numbers:
"PS0SXSSXA")

4-6609940-7

(Alias Part Numbers:
"PM0SXSH3A")

4-6609950-9

(Alias Part Numbers:
"PSL0XSSX0")

6609101-5

(Alias Part Numbers:
"PS00XS000")

4-1609151-7

(Alias Part Numbers:
"C2232A")

3-6609946-0

(Alias Part Numbers:
"PSJSXSSX0")

6609929-7

(Alias Part Numbers:
"PE0SXDHX0")

5-6609951-0

(Alias Part Numbers:
"PS0SXSH6B")

5-6609940-8

(Alias Part Numbers:
"PM0SXSSX0")

6609929-4

(Alias Part Numbers:
"PE0SXDHXA")

Product Affected

6609103-1

(Alias Part Numbers:
"PE0SXSH30")

6609105-5

(Alias Part Numbers:
"PS00XSBX0")

4-6609940-0

(Alias Part Numbers:
"PM0SXDS6B")

3-6609940-6

(Alias Part Numbers:
"PM0SXDS3B")

4-6609961-7

(Alias Part Numbers:
"PSJSXSBX0")

6-6609930-5

(Alias Part Numbers:
"PE00XSS6B")

4-6609959-9

(Alias Part Numbers:
"PM0SXDBXB")

5-6609930-2

(Alias Part Numbers:
"PE00XSH6A")

3-6609940-4

(Alias Part Numbers:
"PM0SXDSX0")

6609952-6

(Alias Part Numbers:
"PS00XDHXB")

3-6609940-2

(Alias Part Numbers:
"PM0SXDSXB")

3-6609940-5

(Alias Part Numbers:
"PM0SXDS3A")

6-6609940-4

(Alias Part Numbers:
"PM0SXSS6B")

4-6609930-2

Product Affected

(Alias Part Numbers:
"PE00XDS6B")

3-6609940-0

(Alias Part Numbers:
"PM0SXDH60")

6609929-5

(Alias Part Numbers:
"PE0SXDHXB")

5-6609940-1

(Alias Part Numbers:
"PM0SXSH6A")

6609104-2

(Alias Part Numbers:
"PE00XSS60")

3-6609952-4

(Alias Part Numbers:
"PS00XSS3A")

6-6609940-6

(Alias Part Numbers:
"PM0SXSS60")

4-6609951-3

(Alias Part Numbers:
"PS0SXDSX0")

5-6609107-4

(Alias Part Numbers:
"PS0SXDS3A")

6609107-6

(Alias Part Numbers:
"PS0SXDS30")

6609102-2

(Alias Part Numbers:
"PM0SXDBX0")

6609101-6

(Alias Part Numbers:
"PS00XD000")

5-6609947-3

(Alias Part Numbers:
"PSJ0XDS60")

3-6609946-5

(Alias Part Numbers:

Product Affected

"PSJSXSS6A")

6-6609941-2

(Alias Part Numbers:

"PM00XDHXB")

6609152-9

(Alias Part Numbers:

"C1144Z")

4-6609951-0

(Alias Part Numbers:

"PS0SXDH6B")

6609106-2

(Alias Part Numbers:

"PS0SXDH30")

6-6609941-9

(Alias Part Numbers:

"PM00XDH6A")

6-6609959-2

(Alias Part Numbers:

"PM0SXS000")

4-1609152-1

(Alias Part Numbers:

"C2229A")

6609929-8

(Alias Part Numbers:

"PE0SXDH3B")

5-6609947-0

(Alias Part Numbers:

"PSJ0XDS6A")

5-6609930-5

(Alias Part Numbers:

"PE00XSH60")

6609107-2

3-6609951-6

(Alias Part Numbers:

"PS0SXDHXB")

5-6609959-4

(Alias Part Numbers:

"PM0SXD000")

5-6609107-6

(Alias Part Numbers:

Product Affected

"PS00XSS6B")

4-6609940-3

(Alias Part Numbers:

"PM0SXSHXA")

4-6609959-8

(Alias Part Numbers:

"PM0SXDBXA")

4-6609106-4

(Alias Part Numbers:

"PS00XDHXA")

6609105-8

(Alias Part Numbers:

"PS0SXDBX0")

6609152-1

(Alias Part Numbers:

"C1027Z")

6609105-2

(Alias Part Numbers:

"PS0SXSBX0")

6-6609107-8

(Alias Part Numbers:

"PS0SXDS6B")

6609153-6

(Alias Part Numbers:

"C1011Z")

6609153-2

(Alias Part Numbers:

"C1005Z")

4-6609107-2

(Alias Part Numbers:

"PS00XSS6A")

5-6609940-9

(Alias Part Numbers:

"PM0SXSS3A")

6-6609107-7

(Alias Part Numbers:

"PS0SXDS6A")

6-6609940-2

(Alias Part Numbers:

"PM0SXSS30")

Product Affected

5-6609963-3

(Alias Part Numbers:
"PS00XDBX0")

5-6609107-3

(Alias Part Numbers:
"PS0SXDSXA")

4-6609940-8

(Alias Part Numbers:
"PM0SXSH3B")

5-6609940-4

(Alias Part Numbers:
"PM0SXSH60")

6609942-5

(Alias Part Numbers:
"PM00XSS6A")

6-6609940-3

(Alias Part Numbers:
"PM0SXSS6A")

6-6609107-9

(Alias Part Numbers:
"PS0SXSS3B")

6609106-5

(Alias Part Numbers:
"PS00XSH60")

3-6609946-8

(Alias Part Numbers:
"PSJSXSS60")

4-6609106-0

(Alias Part Numbers:
"PS0SXSH3B")

6-6609930-3

(Alias Part Numbers:
"PE00XSS30")

4-6609107-8

(Alias Part Numbers:
"PS00XSSXA")

6609103-4

(Alias Part Numbers:
"PE0SXSH3B")

4-6609940-2

Product Affected

(Alias Part Numbers:

"PM0SXDS60")

4-6609951-6

(Alias Part Numbers:

"PS0SXSHXB")

5-1609151-9

(Alias Part Numbers:

"C1173A")

5-6609107-9

(Alias Part Numbers:

"PS0SXSS6B")

5-6609940-6

(Alias Part Numbers:

"PM0SXSSXB")

6609153-3

(Alias Part Numbers:

"C1006Z")

5-6609959-8

(Alias Part Numbers:

"PM0XSXBX0")

5-6609940-5

(Alias Part Numbers:

"PM0SXSSXA")

3-6609952-2

(Alias Part Numbers:

"PS00XSSXB")

5-6609940-2

(Alias Part Numbers:

"PM0SXSH6B")

4-6609929-0

(Alias Part Numbers:

"PE0SXSS60")

4-6609930-1

(Alias Part Numbers:

"PE00XDS6A")

5-6609930-6

(Alias Part Numbers:

"PE00XSSXA")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.